

Mixing glass shards with carbon powders so as to permit adhesion of the carbon powders to the surface of each glass shard



Heating the glass shards so as to melt the surface of each glass shard



Cooling the heated glass shards



Removing the carbon powders from the glass shards

FIG. 1




FIG. 2




FIG. 3





FIG. 4



First Heating Section

FIG. 5




FIG. 6